

## The response from the TCCA to the safety recommendation

The Japan Transport Safety Board received the response from the Transport Canada Civil Aviation (TCCA) to the safety recommendation issued on Aug. 27, 2010 as attached regarding an serious incident of JA847C (Bombardier DHC-8-402) operated by Japan Air Commuter occurred at approximately 6km NNW of Tanegashima Airport on Mar. 25, 2009.

### JTSB safety recommendation to the TCCA

In view of this serious incident, the Japan Transport Safety Board recommends that Transport Canada Civil Aviation (TCCA) give careful consideration to the following and take necessary measures thereof :

- (1) Considering the detrimental effect on safety brought about by the inclusion of impurities in the RGB helical input gearshaft of the engine involved in this serious incident, P&WC, the manufacturer of the engine, should make company-wide efforts including the management of the metal stock supplier and component manufacturer serving P&WC, towards improved quality control concerning the production of the RGB helical input gear shaft.
- (2) P&WC assigned a hazard severity of “Significant – Level 3” to this serious incident by considering only the occurrence of an IFSD as the basis for the risk level determination, but the actual conditions included the loss of all functions of the feathering system for the propeller of the shutdown engine in addition to the engine in IFSD.

The risk assessment of this serious incident should not be made only on the engine necessitating an IFSD, but instead the incident must be reassessed from the viewpoint of the safety of the entire aircraft, and safety improvement actions should be taken if the results of the reassessment indicate this to be necessary.



Transport  
Canada  
Civil Aviation

Transports  
Canada  
Aviation Civile

Tower C, Place de Ville  
5<sup>th</sup> Floor  
330 Sparks Street  
Ottawa, Ontario  
K1A 0N8

Tour C, Place de Ville  
5<sup>e</sup> étage  
330, rue Sparks  
Ottawa (Ontario)  
K1A 0N8

**FEB 06 2013**

*Your file    Votre référence*

(Name)

Senior Technical Analyst  
Transportation Safety Board of Canada  
200 Promenade du Portage  
Place du Centre, 4th Floor  
Gatineau, Quebec  
K1A 1K8

*Our file    Notre référence*

AARQ 5002-A09F0048  
RDIMS 8169128

(Name)

**SUBJECT: Draft Japan Transport Safety Board Aviation Investigation Report  
A09F0048  
Serious Incident- Failure of Engine  
Japan Air Commuter Co., Ltd.  
Bombardier DHC-8-402, Japan Registration JA847C  
Tanegashima Airport, Japan  
25 March 2009**

This is in response to your communication in regards to the above-mentioned final report dated August 27, 2010. The appropriate officials have reviewed the subject report and the attached comments are provided for the Board's consideration.

Should TSB officials have any questions concerning this response, please contact  
(Name and phone)

Yours sincerely,

(Original signed)

Director General, Civil Aviation

Canada

**Transport Canada's Representations to the Draft Japan Transport Safety Board  
Aviation Investigation Report A09F0048, Serious Incident- Failure of Engine  
Japan Air Commuter Co., Ltd., Bombardier DHC-8-402, Japan Registration JA847C  
Tanegashima Airport, Japan, 25 March 2009**

---

**Safety Recommendation (1)**

**Page 21**

The reports states, "Considering the detrimental effect on safety brought about by the inclusion of impurities in the RGB helical input gearshaft of the engine involved in this serious incident, P&WC, the manufacturer of the engine, should make company-wide efforts including the management of the metal stock supplier and component manufacturer serving P&WC, towards improved quality control concerning the production of the RGB helical input gear shaft."

Pratt &Whitney Canada along with Fiat Aero (RGB manufacturer) and Carpenter (Raw material supplier), has reviewed the report. The procedure for future procurements has been enhanced in order to minimize similar raw material inclusion.

Transport Canada is satisfied the new procedure has mitigated the risk of a reoccurrence and is not pursuing further action at this time.



Transport  
Canada  
Civil Aviation

Tower C, Place de Ville  
5<sup>th</sup> Floor  
330 Sparks Street  
Ottawa, Ontario  
K1A 0N8

Transports  
Canada  
Aviation Civile

Tour C, Place de Ville  
5<sup>e</sup> étage  
330, rue Sparks  
Ottawa (Ontario)  
K1A 0N8

**DEC 21 2012**

(Name)

Senior Technical Analyst  
Transportation Safety Board of Canada  
200 Promenade du Portage  
Place du Centre, 4th Floor  
Gatineau, Quebec  
K1A 1K8

(Name)

Your file Votre référence

Our file Notre référence

AARQ 5002-A09F0048  
RDIMS 8033910

**SUBJECT: Japan Transport Safety Board Aviation Investigation Report  
A09F0048  
Serious Incident- Failure of Engine  
Japan Air Commuter Co., Ltd.  
Bombardier DHC-8-402, Japan Registration JA847C  
Tanegashima Airport, Japan  
25 March 2009**

This is in response to your email of April 22, 2010, in regards to the above-mentioned report. TCCA initially responded to the proposed draft recommendation #2 stating that it was in agreement with the conclusion reached by the JTSB regarding the requirement to reassess the impact of a dormant failure in the propeller auxiliary feathering system on the safety of the aircraft.

TCCA has subsequently reviewed the Risk Assessment provided by Bombardier and the pertinent information from the propeller original equipment manufacturer, Dowty, with reference to Dash 8 Series 400 propeller auxiliary pump failure and its impact on the safe operation of the aircraft. The data indicates that the Dowty propeller on the Dash 8 Series 400 aircraft is counterweighted and consequently, the loss of pitch change oil pressure causes the propeller to drive instantly and automatically to a safe high pitch. If there is also loss of engine power, as was the case in this incident, the windmilling drag will not be hazardous as the adverse impact on the controllability of aircraft is minimal.

Canada

The Auxiliary Feathering Pump is necessary to move the propeller to full feather (nominally zero windmilling rotation), not to achieve low windmilling drag. Analysis shows that the difference in drag between a counter-weight coarsened propeller blade pitch and a fully feathered propeller results in an AFM performance gradient decrement of no more than 0.5% (0.005) when a hydraulic pitch change pressure loss occurs at high power lever angle (PLA) settings.

On July 21, 2010, Bombardier revised the Aircraft Operating Manual though TR AOM DASH 8-Q400 to add the above mentioned AFM performance gradient decrement information. Also, Dowty Propellers issued Service Information Letter SIL E338 (Nov. 9, 2010) to underline the minimal impact on the safe operation of aircraft as a result of an auxiliary pump failure.

After careful consideration of this information, TCCA believes that a failure of the auxiliary feathering pump on the Dash 8 series 400 aircraft with the installation of a Dowty propeller is not an unsafe condition and therefore, does not warrant any mandatory corrective action at this time.

Should TSB officials have any questions concerning this response, please contact  
(Name and phone)

Yours sincerely,

(Original signed)

Director General, Civil Aviation